


Men's XL



TIP OF FINGER

8 in (20.3 cm)

3 3/4 in (9.5 cm)

CREASE IN WRIST

* TO INSURE PROPER FIT.

1. MEASURE FROM TIP OF MIDDLE FINGER TO THE CREASE IN WRIST ON PALM SIDE OF HAND.

2. MEASURE WIDTH OF HAND ACROSS PALM JUST BELOW FINGERS.

3. FOR THERMAL FINS & HD GLOVES GO UP 1-SIZE